

Thursday June 3, 1965

Sec Cor $\frac{15}{22} | \frac{14}{23}$ T30N R22W

Highway Maint crew working on TH 96
had to take out I.P. that was simple
on Sec corner.

We have tied it in by Transit
ties so it can be replaced.

There was a Mon lying near by which
has been washed out previously of I.P. rest
on corner

will be replaced Friday afternoon or Monday
do you want us to replace I.P. (or Mon) out
do you want to Supervise replacement.

10:05

Frank Kvidera

talked to Bob Clark 223-4205

he will call back after he has checked with Frank
Kvidera - Survey crew Supervisor to see if that is one he has
replaced rec.

10:10 Called back ^{F.K. is in White Bear} as soon as Frank calls in

He is going to have Frank go to Job site TH96 e.
& check with crew there. check his ties to
sure & decide if I.P. is to go back or Monument
He will call back here after he has found out
from Frank what's to be done. (6-4-65) (Black Top Monday -)

Thurs June 10 1965

Country is going to replace
Sec Corner.