

S.W. CORNER SEC. 12-30-22

MONU. NO. 123

Found R.R. spike set by Frank
Kvidera (Co. Hwy. Dept.).
Dug down 0.9' ft. and found
granite monu. cracked. Placed
Cast Iron monu. over top,
May 17, 1974.

Re-tied June 28, 1974.

Re-tied monu. Feb. 29, 1984.

Checked Ties 6/12/88

RATIED 11-05-04

DOWN 0.5 FT.

RETIED MONUMENT,

7-27-09

123

SEE BTWN. PAGES 129 & 130 FOR 123-E

15" Ash
(MHD SRP disc.)

18" Ash
(MHD SRP disc.)

14" Ash
(M.F.D.)

