

EAST 1/4 COR. SEC. 15-30-23

Monu. No. 134

Found iron in concrete. Granite
down 0.24 ft. Placed bolt
and cast iron cap. 7-17-75

Retied 7-28-75.

Removed for reconst. of Lex. Ave.

Replaced monu.

Retied monu. 5-4-90

Added cement to top. 10-1-97

Added Cement to Top 4/8/00

Retied monu. 3-20-01

Removed & lowered C.I., set 12" dia. tube
for maint. 4-30-02

Tied monu. 07-19-07

Checked condition of L.I.M. in C.I.M.H.
assembly and ties. 8-15-12

