

EAST 1/4 COR. SEC. 13-30-23
MONU. NO. 138

Found re-bar ($5/8$ " in pavement.
and tied. Placed by M.W.
Carley. 1974.

Found $1/2$ " iron in $3/4$ " iron in conc. and
5" steel pipe down 12"; set
12" dia. manhole over $3/4$ " iron;
 $1/2$ " iron bent was removed. 6-15-01

Dug in suspected area (6×17.8) &
an area (1.5×6) in SW cor.
of 1st area to a depth of 3.9
ft. Found nothing. Maint. Dept
backhoe & crew filled in
area with bit. [See Sec. 13-30-23] 7-17-01

Raised MH assembly up 2" for new
lift to be added. 9-23-02

TIED MONT,
Retied monu.

2-25-05
8-11-10

138

