

16^{MOF}₁₄₀₆
 SW. COR. SEC. ~~17~~ T30, R23
 MONU. NO. 155

Found granite down 0.16 ft. 8-21-74

Set cast iron cap. 5-17-76

Twenty (20") inch cast iron set
 after reconstruction of road
 by Co. Const. Dept.

Tied monu. 6-13-90

Retied monu., Top missing. 7-13-98

Removed C.I.; set 20" C.I. & MH. 7-21-98

RETIED MONU 2-15-05

Retied monu. 7-19-10

