

NE. CORNER SEC. 6-30-22

MONU. NO. 155P  
(155C)

Found granite tipped, down 0.3'; also found 2 P.K. nails and a nail and disc none of them located over tipped (all east of tipped granite, did not tie out any). Dug granite up and uprighted but does not fit ties. Ties & P.K. between tipped granite and up-righted granite. Up-righting moved granite top east. May 15 and 16, 1974. Place cast iron cap. July 25, 1975. Re-tied monu. March 22, 1976. Tied monu. for road const. April 1990. Removed C.I. cap. 5-90. Placed 20" cast iron monu. Sept. 5, 1990. Retied monu. 1-27-93. Set 20" C.I. marked "3RD CORR. LINE" 4.19 ft. N. of closing corner (granite loc.) 7-27-95. Tied 155P monu. 9-25-98. Retied 10/11/05

