

S. E. COR. SEC. 14, T30, R23

MONU. No. 161

Found cast iron monu. on side
slope flush. Re-tied 1-28-76.

Monu. reported leaning south. 1991.

Removed monu. April 15, 1997.

Set 3" disc in conc. 9- -1997

Retied 3" alum. disc. 3-20-01

Retied monu. 7-29-10

161

