

5/4 COR. SEC. 20, T30, R23
MONU. No. 204

Found cast iron monu. flush.
Re-tied Feb. 13, 1976.
Destroyed by construction in 1980;
ties in folder.
Replaced with 20" cast iron.
Retied monu. 6-19-91
Retied monu. 11-21-02
Retied monu. 07-30-07
Checked monument and ties, found a
C.I.M. shaft only, top broken off, down
0.3 ft. in bit road. 7-30-12

