

5/4 COR. SEC. 21-30-22

MONU. NO. 218

Found granite monu. down 0.1 ft. in centerline Centerville Road. June 12, 1974.

Re-tied June 24, 1974.

Removed cap for const. 6-20-84.

Granite down 1" only. 6-26-87

Retied monu. 5-1-90

Retied monu. 6-25-98

Tied monu. for removal by Const. Proji. 12-4-01

Reset 20" C.I. monu. down

Reset monu. loc.; set 20" C.I. 18" down.

Contractor to set pipe & MH assembly. 8-22-02

RETIED MONT 3-23-05

Retied monu. 7-15-10

