

E 1/4 COR. SEC. 25, T30, R23  
MONU. No. 238

Found P.K. nail in surface  
black top. Found 1/2" I.D. iron  
1.38' long down 1.19'.  
Found old road surface  
down 2.9 ft. with 1 1/2" dia  
iron in old pavement. 7-1-75  
Placed 20" cast iron monu. 7-7-75  
Retied monu. 12-20-91  
Monu. down 5"; set 4 5/8" C.I. over  
top and cemented in. 10-13-93  
Retied monu. 12-04-02  
RETIED MONU. 8-24-07  
Found a C.I.M flush in bit, road top  
worn, checked condition of ties; 9-6-12

