

SOUTH 1/4 COR. SEC. 30-30-23  
 MONU. No. 252

Found odd sized iron. July 1974.

Tied-out Iron which is approx.  
 .15' below surface, there  
 appears to be a metal plate  
 with a hole in the middle  
 over said Iron. 6-27-91

Construction removed monu. 1995

Contractor set manhole. 1996

Reset monu. location; set P.K's. 9-3-97

Set 20" C.I. down 14" ±. 6-1-98

Retied. 7-31-98

Retied 10/24/05

Retied monu. 7-23-10

252

