

5 1/4 COR. SEC. 29, T30, R22

MONU. NO. 266

Found granite down 0.5 ft. 4-74

Set short C.I. over and retied. 7-31-75

Retied monu. & removed C.I. 5-13-91

Relocated position & checked ties. 9-27-91

Set 20" C.I. monu. 10-14-92

Retied monu. 12-08-00

RETIED MONU. 8-29-06

Found center of shaft of broken C.I.M.

down 7-1 ft. Checked ties. 8-20-10

Set 4-3/8 in. C.I.M. over broken C.I.M.,

in concrete; flush in bituminous road.

Tied monument. 9-29-10

MON 266N ties found between 269 and 270

266

