

EAST 1/4 COR. SEC. 31, T30, R23
MONU. No. 278

Found nothing, ties gone. Placed
a cast monument. 5-6-76

Retied. 1989.

New Brighton street const. destroyed monu.

Reset 20" C.I.M. flush, cemented
monu. & retied. 10-29-99

Retied 10/24/05

Retied monu. 7-23-10

