

EAST 1/4 COR. SEC. 36, T30, R23  
 MONU. No. 288

Found R.P. spike at surface;  
 Found granite monu. down  $4\frac{1}{2}$ ";  
 Placed short C.I. Dec. 14, 1979  
 Cast iron down 0.3'; Tied 6-6-90.  
 Retied monu. 12-04-02  
 Retied cast iron monu. down 0.25ft., 6-17-09

288

