

SOUTH 1/4 COR. SEC. 33-30-22  
 Monu. No. 318

Found granite monu. down 0.4  
 ft; placed C.I. cap and  
 bolt over granite and re-tied. <sup>9-15-</sup><sub>-74</sub>  
 Granite in wrong place; removed cap  
 and placed 20" cast iron monu;  
 wrong loc. approx. 1926. May 1984.  
 Tied out cast iron for maint. const.  
 March 27, 1990.

Removed 20" C.I. April 10, 1990.  
 Maintenance removed granite. May 3<sup>rd</sup>, 1990.  
 Relocated position for cast iron  
 and placed 6" spk. for old  
 granite monu. (incorrect loc. 1/4 cor.)  
 7-13-90

Retied correct position. 7-16-90  
 Placed 20" C.I. 7-20-90  
 Retied. 9-20-99  
 RETIED mont 6-20-06  
 Retied mont 7-29-11

Checked:  
 6-24-77

