

WEST 1/4 COR. SEC. 2, T29, R23  
 Monu. No. 332

Found granite down 0.89 ft. Set  
 10" C.I. over Sept. 26, 1975.

Destroyed by construction; set 20"  
 C.I. monu. Sept. 1980.

Retied monu. 6-5-81.

Retied monu. 1-18-91

Retied monu. 7-17-02

Monu. Near of Repair Removed LOOSE  
 BITUMINAS from AROUND Monu. AND  
 Replaced with quick "set 45" CONC.  
 10/27/05

RETIED Monu 8-24-07

Checked condition of L.I.M. flush in  
 bit road and its ties. 6-12-12

Checked:  
 4-17-77

