

CENTER SECTION 6-29-22

MONU. NO. 337

Found Cast Iron broke off. Replaced
with new cast iron flush and
re-tied Aug. 16, 1974.

Retied. 11-27-90

Relocated position 4-20-95

Set 20" C.I. 1995

Retied monu. 7-31-98

RETIED MOUNT. 6-27-06

NEW CONC. AROUND MOUNT. 8-10-06

Retied monu. 7-12-11

337

checked:
9-12-77

OLD TIES
NOT CHECKED

