

CENTER SEC. 9, T29, R22
 Monu. No. 387

Found $\frac{3}{4}$ " iron flush and re-tied.

Used old ties from Ray Wolfgram's notes; checked location; see section folder; placed cast iron monument.

Cast iron destroyed; re-set mon. 1980.

Found mon gone; found C.I. down 12" in wrong place; moved to correct position and re-tied. July 30, 1981.

Checked Aug. 9, 1990

Retied monu. 4-9-03

Monument missing; established position using ties. Set a 20 inch C.I.M. in concrete flush in bituminous road 9-29-10

Tied monu. 10-1-10

387

O.T. = Old Tie

