

CENTER SEC. 12-29-22

MONU. NO. 393

Found 19" long $\frac{3}{4}$ " dia. pipe.

Dug down 2 ft. below ditch.

Placed iron back. Aug. 30, 1974.

Compute center of section ($1.5 \pm$ south of iron) and dug $4.3 \pm$ ft. Found nothing more. March 26, 1976.

Placed C.I.M. at computed intersection, placed guard post and sign and tied out.

C.I.M. is approx. $1.4'$ south of found Iron. (6-3-91)

Retied monu. 10-18-00

TIED OUT FOR CONST. REMOVAL 11-06-06

RESET 20 IN. CAST IRON IN CONCRETE; PLACED

SIGN AND POST 1.5 FEET SOUTHWAY 11-19-07

Retied monu. 8-11-10

393

