

N.E. COR. SEC. 15, T 29, R 23  
MONU. NO. 401

Found P.K. Checked location.  
(See Survey Book #1, Page 21 & 23)  
Placed cast iron monu.

Re-tied monu. July 28, 1975.  
Destroyed by road construction; replaced  
monu. April, 1981.  
Tied monu. and set 20" C.I. 1.5'  
below grade. 4-15, 29, -98  
Set MH over C.I. 7-24-98  
Retied monu. 8-10-99  
Retied monu. 7-11-06  
Retied monu. 6-20-11

Checked  
7-29-77

SE bolt Signal  
Lite  
(Punch)

SW bolt Signal  
Light  
(Punch)



MON 402

CO.

RD.

AVE.

LEXINGTON

