

SOUTH 1/4 COR. SECTION 15, T29, R23
Monu. No. 446

Found granite monu. 6-18-76

Tied granite out for removal by
Const. 4-26-00

Set 20" casting iron down 18"; Shafer
Contracting to set pipe and MH
assembly. 7- -00

Retied; monu. down 18"±. 3-28-01

RETICO MONT 9-05-07

Found "Ramsey County" L.I.M. in L.I.M.H
assembly. Checked condition of ties. 10-3-12

446

