

S. E. COR. SECTION 15, T29, R23

Monu. No. 447

Re-established location by surveys
from City of St. Paul. 1979

Placed short $4\frac{5}{8}$ " C.I.; Aug. 17, 1981.

Removed C.I. for Const. 4-28-00

Reset 20" C.I.; Shafer Contr. to set
12" tube and MH assembly. 8-15-00

Retied; monu. down 15". 3-28-01

RECTICO MONT 9-05-07

Checked condition of C.I.M. in L.I.M.H.
and ties. 8-15-12

447

