

SOUTH 1/4 COR. SEC. 5-30-23
 MONU. NO. 54

Found Cast Iron down 0.13 ft
 and re-tied Aug. 8, 1974.
 Monu. destroyed by construction;
 replaced with 20" C.I. and
 cemented it in. June 7, 1988.

Retied monu. 5-17-90.
 Retied monu. 2-22-99
 RETIED 12-29-04
 RETIED MONUMENT 10-19-09

