

N 1/4 Cor. Sec. 13, T28, R22
Menu. No. 692

Found granite down 0.4±ft. Set
short cast iron monu. Re-tied
monu. Feb. 18, 1976.

Short C.I. gone; granite down 4 1/2" ±.
11-15-90

Tied monu. 5-8-96. Maint to remove
granite monu.

Maint. Dept. set manhole on cast
in place 6" thick conc. cylinder.
Found water seeps into MH;
tried boring 4" dia shaft and
filled with sand. Water problem
persists. 8-1997

Filled MH with sand & set 20" C.I.
with cover on top. - -98

Retied C.I. down 3" ± in MH. 4-18-01
Monument lost to Housing Development
Project Replaced Monument by using
Traverse Notes and Ties. Placed Markers
Casting Assembly around Cast iron. 9/14/05
Reties Sept 14, 2005.

Retied monu. 7-28-10

692

