

SOUTH 1/4 COR. SEC. 13-28-22
MONU. NO. 738

Found Cast Iron monu. down
6" and re-tied Aug. 6, 1974.
Frank Kridera, Co. Hwy. Dept,
notes show granite monu.
underneath. Cast iron marked
"MINN HWY. DEPT. MONU."

Monu. covered by 4" bituminous. Set
P.K.'s; monu. down 0.6't. 8-9-89.

Tied monu. (flush). 1-7-03

Retied monument, flush in bit., 5-21-08

Found "Ramsay County" C.I.M., flush in
bituminous road; checked condition of ties
4-29-13

