Donald W. Schmidt, Minnesota Registered Surveyor No. 10459, hereby certifies to Crown Life Insurance Company, Pearson Candy Company and Title Services, Inc., that the foregoing is a true and correct representation of the boundaries and area of the following 344" won found 0.1 Horth 40 0,25 west (Parcel 1) Lots 1 and 2, Block 6, Kentucky Terrace, including that part of the Southeasterly 1/2 of adjoining Benson Street, vacated, lying between the extensions across it of the Southwesterly line of said Lot 2 and the most Easterly line of said Lot 1. Subject to the easements and rights reserved by Section 228 of the St. Paul Legislative (Parcel 2) Lots 9 to 13, inclusive, Block 3, Kentucky Terrace, including that part of the Northwesterly 1/2 of adjoining Benson Street, vacated, lying between the extensions across it of the Southwesterly line of said Lot 9 and the most Easterly line of said STREET Lot 12. Subject to the easements and rights reserved by Section 228 of the St. Paul Legislative Code. (Parcel 3) Except Rankin Street, all that part of the following described tract lying Northeasterly of Rankin Street of the East 1/3 of the Southeast Quarter of the Southwest quarter lying Southerly of West 7th Street and Northwesterly of a line drawn from a point on the East line of said tract where the same is intersected by the Southeasterly line of Rockwood Avenue to a point on the South line of said tract where the same is intersected by the said Southeasterly line of Rockwood Avenue; part of Section 15, Township 28, Range 23. SEVENTH (Parcel 4) That part of Rockwood Avenue, vacated, adjoining Block 13, all in Palisade Addition to Saint Paul, lying Northeasterly of the extension across said street of the Southwesterly line of said Block 13. Reserving to the State of Minnesota, in trust for the taxing districts concerned, all minerals and mineral rights, as provided in Section 10, Chapter 386, Laws of 1935. Subject to easement for purposes of obtaining access to and operation of gate valves on the private water main on parcel 3 dated October 22, 1968, filed November 21, 1968 as Document No. 529573. Subject to easement for slopes, cuts and fills in the grading of Rankin Street filed as Document Nos. 400059 and 505366. 17777777777777777777777260,577777777777 Subject to easement to Northern States Power Company filed January 15, 1969 as Document No. 531830. and of the location of all buildings and other improvements situated thereon; location and name of all public streets or alleys located thereon or adjacent thereto; location, dimensions and recording data of all easements as per title binders furnished location and dimensions of all unrecorded easements visible thereon; location of applicable building setback lines required by local ordinances and regulations if available; and location of all visible encroachments onto or from said lands. The undersigned further certifies that this survey was made under his direct supervision and that he is a duly registered Land Concrete Dock with Awning Surveyor under the Laws of the State of Minnesota. Stand Pipe -Valves Minnesota Registered Surveyor No. 10459 Right of access retained on property as per LAWN * Title Binder: Chicago Title Insurance Company File No. 100678 Dated Dec. 08,1982 FLOOD PLAIN - Zone X (Area Determined to be outside 500 year flood plan as FACTORY per Flood Insurance Rate Map - National Flood Insurance Program) 1 STORY ZONED I-1 (Industrial 1) - See enclosed Zoning Code, Map and Legislative Code PRE-CAST CONCRETE OFFICE Front (Street side) setback- 12 time hieght of building, max. height bldg.=50' 1 STORY BRICK& GLASS Side & back yard setback- 0 (zero) feet where adjoining land is zoned I-1 (Property East and South are also zoned I-1) Alley in Block 6, Kentucky Terrace, vacated - (Does not show up in description.) Easements (recorded) shown as per Title Binders furnished. Section 228 of St. Paul Legislative Code refers to vacated streets and alleys and such reservation of needed easements relative to implace utilities. Not furnished. Document Nos. 400059 & 505366 refer to slope & fill easements for construction of Rankin Street - Rankin St. is graded and paved. (Cuts & fills per drawings furnished not shown). Blacktop Walk Trees and hedges not located or shown.

All signs not located or shown.

o Denotes iron pipe monument set in 1982.

o Denotes iron found inplace in 1982.

o Denotes power pole (PP)

o Denotes light pole (LP)

Also not located portable conc. curb, landscaping, bldg utility pipes.

1" snow on ground at time of survey 1/04/90 * Southerly line taken as NEly Extension of SEly line of Rockwood Air in Palisade Addn. par old survey. 2 STORY Visible Apparent Eucroach mants: Parking at NW cov. of property by Alley. Powar Poles & Overhead lines on East Eaves on 2 Apts. NW Corner Guy pola & lina Wast Sida Contains 8.98 acres, more or less: Manholes O+-Catch Basin SCALE: 1"= 50 GRAVEL BOUNDARY AND LOCATION MAP PEARSON CANDY COMPANY South Quarter Corner Section 15, T.28N, R.23W ST. PAUL, RAMSEY CO., MINNESOTA South line of SW1/4 of Sec. 15, 28, 23 **GEORGI-SCHMIDT & ASSOC. INC.** Land Surveyors 3092 N. Lexington Ave. 483-4408 ROSEVILLE, MINNESOTA 55113 December 12, 1982 January 15190 - Added Flood Plain Zone Jone 6, 1990) Add Title Services