

Book #63 - Dr. #8

OFFICE OF COUNTY ENGINEER
RAMSEY CO. MINN.

Location Survey

ROUND LAKE PUMP

From..... To.....

Road Acc't. No.

Date Filed.....

File.....

15° F.
Cloud Cold.

{ Don Weber
Dave Skooglen
Jim Bell.

Proposed Pump
Locations
Round Lake

Feb. - 1934

Lake Improvement
Round Lake Pump

13m 231 926.37 924.06

B.M. 0.82 919.90 7.29 919.08

0+00 $\angle$ Road 18.0

+20 16.7

+23 13.9

+50 12.7

10.5

+50 7.0

T.P. 2.08 909.34 12.64 907.26

2 4.2

+50 1.4

Section
1-5

LEFT $\angle$ RIGHT

Spk in T.P. int. Vermont + L. Canada Rd.

" " " " " " " " " "

1.9

$$\frac{2.8}{5} \quad 3.2 \quad \frac{3.2}{5}$$

$$\frac{3.0}{5} \quad 6.0 \quad \frac{6.0}{5} \quad \frac{5.7}{6}$$

$$\frac{4.5}{5} \quad 7.2 \quad \frac{5.2}{3} \quad \frac{5.2}{5}$$

$$\frac{8.4}{5} \quad \frac{8.5}{2} \quad 9.4 \quad \frac{8.3}{3} \quad \frac{8.4}{5}$$

$$\frac{13.1}{5} \quad 12.9 \quad \frac{12.2}{5}$$

$$\frac{5.1}{5} \quad 5.1 \quad \frac{5.1}{5}$$

7.9

BM. 1.53 925.59 ✓ 924.06 ✓
 0+00 £ Little Canada Road. 23.0

+20 22.6

+34 21.2

+50 18.3

+65 16.1

+83 13.0

T.P. 1.39 914.90 ✓ 12.08 913.51

1 8.7

+38 P.O.T. 4.4

T.P. 3.40 907.91 ✓ 10.39 904.51

2 99.2

+50 96.5

Depr. Bottom Lake 12.1 895.81 ✓

Section
 10.5
 10.5
 10.5

Lt Lt Lt

Spt in T.P. int Vermont + L.C. Rd.

$$\frac{2.8}{30} \quad 2.6 \quad \frac{3.3}{30}$$

$$\frac{2.6}{30} \quad \frac{3.1}{15} \quad 3.0 \quad \frac{3.6}{11} \quad \frac{5.4}{30}$$

$$\frac{3.0}{30} \quad \frac{3.2}{11} \quad 4.4 \quad \frac{5.4}{13} \quad \frac{4.8}{19} \quad \frac{6.0}{30}$$

$$\frac{3.5}{30} \quad \frac{4.0}{23} \quad \frac{6.3}{11} \quad 7.3 \quad \frac{8.0}{13} \quad \frac{7.0}{19} \quad \frac{7.9}{30}$$

$$\frac{4.6}{30} \quad \frac{5.4}{21} \quad \frac{7.8}{13} \quad 9.5 \quad \frac{10.3}{14} \quad \frac{8.9}{20} \quad \frac{10.1}{30}$$


$$\frac{6.0}{30} \quad \frac{8.5}{18} \quad 12.6 \quad \frac{16.2}{15} \quad \frac{17.5}{30}$$

$$\frac{0.1}{30} \quad \frac{5.0}{14} \quad 6.2 \quad \frac{8.9}{30}$$

$$\frac{7.3}{30} \quad \frac{9.5}{19} \quad 10.5 \quad \frac{12.3}{30}$$

$$\frac{7.0}{30} \quad 8.7 \quad \frac{10.4}{30}$$

$$\frac{10.7}{30} \quad 11.4 \quad \frac{11.5}{30}$$



Proposed Location for Pump.

{ Vermont St }
{ Round Lake Add. }

Feb. 1 - 1934

2

1

0+00

Feb. 1 - 1934

Round Lake
Dry

+70 Flint

+27-8" Pop. 25' + F. Cor.
+15-15" Pop. 7'

+82-12" Tw. Oak. 7'

+57 Cor. Rabbitry 27'
+42 Cor. Rabbitry 30'

← Vermont St.
Bolt. +38. Round Lake Add.

swell spot for pump.

+03-12" Pop. 10'
+94-8" Pop. 24'
+83 Out Ho. 34' 18"
+72 Cor. Ho. 39'

+49 Cor. Ho. 29'

Little Canada

spike. Road
to Rice St

P.L. 17+00
Little Canada Notes.

