

TRACING		SURVEY NOTES				
DRAWER	FILE	DRAWER	FILE	DATE	SPEC.	DESCRIPTION
61	110			-		35 E. X-ING
18	110	12	189	9/3/73		Drainage No. of T.H. 9L
21	109			3-77		ROAD WIDENING, H ² TO No. CO. LINE NOT BUILT
		13-55		1981+		PLAN SURVEY - EDGERTON TO LABORE
26	101			1983		BIKEWAY - Edgerton to LABORE
28	106			4/89		TH 96 to H ² SAP 62-659-05
28	135			11/91		H ² to J SAP 62-659-07
28	136			2/9-1		R/R to H ² SAP 62-659-09
28	135			1999		CENTERVILLE CIR. - MEADOWLANDS DR 62-659-11
11	2F			1971		MNDOT R/W TURN BACK LABORE RD TO CO. RD. F
28	186			2002		HORIZON TO HWY 96 ^{CONST.} S.A.P. 62-659-13
28	201			2002	TBM	HORIZON ST TO HWY 96 ^{ROW.} S.A.P. 174-020-17
28	230			2004	TBM	EDGERTON TO HORIZON O'LAY SAP 62-659-15
28	314			2014	PDF	CO. RD. H-2 TO CO. RD. J S.A.P. 62-659-016 IN HOUSE BIT O'LAY
28	366			2014	PDF.	SAME AS 28-314 IN HOUSE BIT O'LAY
28	411			1993	PDF.	SAULT ST. MARIE RR TO CO. RD. H-2 - ALSO 28-136 SAP 62-659-09