

TRACING		SURVEY NOTES				
DRAWER	FILE	DRAWER	FILE	DATE	SPEC.	DESCRIPTION
23	102	13	101	9-12-75		Signal Revisions @ Edgerton ✓
20	107			11-7-75		STORM SEWER, JACKSON TO I 35E
23	106			2-11-76		Signal Cabinet Diagram @ Edgerton
12	Print 212	12	212	11-1975		Storm Sewer at Adolphus
		14	122	6/15/87		ROSELAWN AVE. - SOO LINE BRIDGE RICE to 1948 E.
27	117			11/4/87		CSAP 62-626-01 T.H. 280±0 CT EVK and
28	117	TBM				RICE to JACKSON SAP 62-626-04 (B.R.A.A.)
28	119	TBM		1991		BRIDGE # 62559 OVER SOO LINE ^{SP} 62-626-03
28	121	TBM		1991		R/W @ SOO LINE SAP 62-626-05
28	170			2002		SIGNALS @ EDGERTON