

Centerville Rd.

1

| | | Dr. | Book |
|---|------------------------|--------------|---------------|
| ✓ Edgerton St. to Birch Lake Blvd. N. | Paving Notes | 1 | 23-03 |
| ✓ " " N. Co. Line | Ditch Survey | 8 | 99 |
| ✓ " " N. Co. Line | Rd. Map " | 10 | 2 |
| ✓ Little Canada Rd. to Edgerton St. | do | 10 | 26 |
| ✓ Rice to Centerville Rd | W.P.A. Plan | 6 | 68 |
| | Pave Sag. 1935 | | 61 |
| ✓ Accident - 700' No. of No. Co. Line Rd. | Survey | 6 | 119 |
| ✓ North Birch Lake Blvd. to No. Co. Line | Plan Survey | 6 | 120 |
| ✓ N. Line Sec 5 N. C. Twp to Sta 31 | Drainage Survey | 8 | 143 |
| ✓ Birch Lake Blvd. N. to Co. Rd. H ² | Plan Survey 1939 | 16 | 25 |
| ✓ CENTERVILLE RD. STA 92+ - H ² | SOUNDINGS 1943 | 16 | 25 |
| ✓ LOW-SPOT LEVELS WILKINSON LAKE | LEVELS 1943 | 16 | 25 |

CENTERVILLE ROAD

2

Edgerton St. to Birch Lake Blvd. No.

Ditch Survey

Edgerton St. to No. County Line.

Little Canada Rd. to Edgerton St.

Rice St. Conn.

700' No. of No. Co. Line to No. Co. Line

Co. Rd. "H²" to No. Co. Line

Little Canada Rd. To Edgerton,

A + N. Co. Line

Paving Notes

Road Map.

" "

W. P. A. Plan

Accident Survey

Plan Survey 1945

Bit. Surface, 1953

Different Curve Aline. ?

| Dr. | Book |
|-----|-------|
| 1 | 23-03 |
| 8 | 99 |
| 10 | 2 |
| 10 | 26 |
| 6 | 68 |
| 6 | 119 |
| 15 | 2 |
| 15 | 52 |
| 15 | 2 |