## **MONUMENT 389E**

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER  A Witness Monument to the Center of Section 10, Township 29 North, Range 22 West, County of Ramsey, State of Minnesota.	
At the corner location shown on the sketch	
🖾 🛘 🗈 August 8, 2006 found a cast iron monument within a cast iron manhole	
assembly.	
□ □n placed a	
SKETCH OF RE	FERENCE TIES
MUNUMENT 389N H S 23,38	NAIL AND DISK
PUNCH MARK TOP OF HYDRANT	IN POWER POLE N17*52'52"E 34.48
GERVAIS MEDIAN 71,83	MEDIAN A VENUE
NAIL AND DISK IN 14 IN. PINE	NAIL AND DISK IN POWER POLE
RAMSEY COUNTY NAD83 (1986)	3 IN LUWER LUCE
MONUMENT 389E '	
X= 589986.430 (Easting) Y= 181334.649 (Northing)	ALL DISTANCES ARE SHOWN IN U.S. SURVEY FEET. BEARINGS ARE FOR TIE REFERENCE PURPOSES ONLY.
Statements of evidence relative to this corner are on the following page(s).	
I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision this day of, 20	OFFICE OF COUNTY SURVEYOR  County of Ramsey  I hereby certify that this document was filed in the County Surveyor's office on the day
SIGNATURE	of, 20
Minnesota License No.	David D. Claypool, P.L.S., County Surveyor
☐ County Surveyor ☐ Land Surveyor	By, Deputy

## **MONUMENT 389E**

Found a manhole at monument location. Put a punch mark in top of manhole by using old ties from the City of Maplewood and County Highway Department. Set witness monument 33 ft. east on the quarter section line. No date given in field book.

Retied monument, April 10, 1975.

Checked monument, August 9, 1990.

Monument destroyed by City of Maplewood; set a 20 in. cast iron monument, October 13, 1992.

Removed cast iron monument for City of Maplewood, June 13, 1997.

Set 20 in. cast iron monument within cast iron manhole assembly at 16.5 ft. east of corner location, May 13, 1998.

Tied monument, April 2, 2001.

Retied monument, August 8, 2006.