MONUMENT 130

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

East Quarter Corner of Section 17, Township 30 North, Range 23 West, County of Ramsey, State of Minnesota.

At the corner location shown on the sketch	
☐ On June 17, 2014 found a "RAMSE"	Y COUNTY" cast iron monument within in a cast iron
manhole assembly, down 1.5 ft.	
☐ raised/lowered	monument removed monument (explain)
☐ On placed a	
A SKETCH OF RE	FERENCE TIES
	\ \(\text{\tint{\text{\tint{\text{\tin}\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\tex{\tex
Puńch mark on top nut	12 J
of hydrant	> RIT
Commercial building	A BOUND RSTATE 3
no. 4749	5
[0] P.	J 35W
	\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\
Nail and Ramsey N73° 42'01" W	Punch mark on
County disk in South face of 24 95	Northwest bolt of advertisement
in. Ash, up 1.9 ft.	S84°48'15"E sign base
SERVICE ROAD à	88.94
07/10	
Center of screw on top	
nut of hydrant	(S)
AAONI INAFNIT 130 Commercial	
MONUMENT 130 Commercial building	0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0
110. 2172	
NAD83 (1986) X= 550381.575 (Easting)	ANail and Ramsey
Y= 207695.267 (Northing)	County disk in West face of power
NAD83 (1996)	pole, up 1.4 ft.
X= 550381.115 (Easting) Y= 207695.763 (Northing)	ALL DISTANCES ARE SHOWN IN U.S. SURVEY FEET. BEARINGS ARE FOR TIE REFERENCE PURPOSES ONLY.
()	
Statements of evidence relative to this corner are on the following page.	
I hereby certify that this survey, plan, or report	OFFICE OF COUNTY SURVEYOR
was prepared by me or under my direct	County of Ramsey
supervision, that I am a duly Licensed Land Surveyor under the laws of the state of Minnesota,	I hereby certify that this document was filed in the
and that this certificate is correct and complete to	County Surveyor's office this 10th day of
the best of my knowledge and belief.	June , 20 <u>15</u> .
Umni/ V. Ben 6-10-15	
Daniel D. Baar Date	(roigW. Humman
Deputy County Surveyor	Craig W. Hinzman, L.S.
Minnesota License No. 45816	Ramsey County Surveyor

MONUMENT 130

١		
-		East Quarter Corner of Section 17, Township 30 North, Range 23 West
	December 16, 1847	Set 1/4 Section post, Bur Oak 12 N28°E 29, "Do" (Bur Oak) 10 S45°W 42, Isaac N. Higbee, Deputy Surveyor.
And the second of the second o	May 27, 1898	In establishing the 1/4 Corner between Sections 16 and 17, this corner was fixed 33 ft. from Skiba's fence, which he claims to be right. Government witness trees gone, Ramsey County Resurvey.
	June 18, 1898	Set monument, Ramsey County Surveyor's Office.
	October 1, 1927	Found an iron pipe, set a brass plug in concrete pavement, as well as two witness monuments consisting of a "X" on 6 in. x 6 in. x 30 in. concrete monuments, N51°46'W a distance of 53.85, and S49°30'W a distance of 51.85. Brass plug set in center of 27 ft. concrete pavement, Minnesota State Highway Commission.
	November, 1943	Checked monument, Ramsey County Surveyor's Office.
	September, 1965	Checked monument, Ramsey County Surveyor's Office.
	August 21, 1974	Found a granite monument down 0.17 ft. and tied, Ramsey County Surveyor's Office.
	October 10, 1974	Placed a cast iron cap and bolt monument, Ramsey County Surveyor's Office.
	May 26, 1993	Retied granite monument down +/-0.3 ft., Ramsey County Surveyor's Office.
	Date Unknown	Removed monument for construction.
The state of the s	June 2, 1998	Set a 20 inch cast iron monument within a cast iron manhole assembly, Ramsey County Surveyor's Office.
	July 7, 2003	Tied monument, Ramsey County Surveyor's Office.
	September 8, 2006	Concrete repair around manhole assembly, Ramsey County Surveyor's Office.
-	September 26, 2008	Retied monument, Ramsey County Surveyor's Office.
	April 23, 2013	Checked cast iron monument within a cast iron manhole assembly, down 1.5 ft., and ties; performed a static GPS observation, Ramsey County Surveyor's Office.
	June 17, 2014	Checked cast iron monument within a cast iron manhole assembly, down 1.5 ft., and condition of ties; performed RTK GPS observations, Ramsey County Surveyor's Office.
ı	/	