

PLEASANT LAKE

18

S.E. Corner brick
fence post

38.66
33.66

S.W. Corner brick fence post

F. Post

39.44
34.32

2477.62

6" maple

31.61

100.97

tree

3 nails in oak
F. Post

41.13

3 nails in
oak F. Post

43.26

1" B.O. 29.77

5" x 4" B.O. 6"

72.61

94.93

25.50

tree

16" B. oak

New ties 9/26/21

N.W. Corner
Headwall of
water works
ditch

2630.14

72.07

tree

92.85
6" B. oak tree

5" x 4" B.O. 6"
F. Post

New ties taken 12/1/07

New ties taken 9/26/21

Found old stake at the South West corner of Section 18 Government witness trees gone
Set monument and tied it Apr. - 1895

In Establishing the $\frac{1}{4}$ corner between Sections 18 and 19 Found one Government witness stump
Fixed corner and tied it March, 1898 Set Mont. May 11 - '98

In Establishing the South East corner of Section 18 Proved, and fixed the Section corner
halfway Government witness trees gone March - 1898 Set Mont. May 11 - 1898