



nothing to the 76

Nail in 34.73
BO Stump

scrub oak • 68.0
cor scale 46.55
153.14 • scrub oak
24.51
SIGN POST

24.16
3336.68

3014"
13010" 58.38
53.20 • 3012"

2649.15
1324.77

2649.15

3315.69 15.69

3294.70
ROAD

BARLOW

57.62 • tree
62.87 • tree

2643.56

2641.32

90°33'
89°27'

15' 80"
42.53
DOWN 6"
42.73
42.86
3010"
38.86 • 3010'
65.78 • 308'

LAKE

3014"
26.19
308" 23.78
6.60 • 3010"

2643.9

0.35
ditch

2648.05

2642.57

1700

244.84 • 3018"
90°32'
204.68 • 3020" BT

1321.20

82.82 • tree
59.45 • ck

2639.10

2636.85

1318.43 1997 • 3010" 1318.43

69.20
308"
HOUSE
170.21
509.14
48.23
308"

91.33 • 3012"

For North East Corner of Section 5 see Section 4 Set Mount. Sept. 15-1900

In Establishing the $\frac{1}{4}$ Corner between Sections 4 and 5 Found our old Government witness stump and also found old stake at $\frac{1}{4}$ corner Fixed corner and tied it
Aug 17-1896 Set Monument June 18-1898

In Establishing the South East Corner of Section 5 See Sec. 4
Found old stake June 15-1898 Set Mount. June 18-98

In Establishing the $\frac{1}{4}$ Corner between Sections 5 and 8 found old stake at $\frac{1}{4}$ corner and our Gov. witness tree Jan 6-1903 and set Mount.

In Establishing the S.W. corner of Sec 5 prorated N and S. and fixed Section cor.
no Gov. ties Jan 21. 1903 and set Mount.

In Establishing the $\frac{1}{4}$ Corner between Sections 5 and 6 prorated N and S. and fixed
 $\frac{1}{4}$ corner no Gov. ties Jan. 20-1903 and set Mount.

In Establishing the N.W. corner of Section 5 Measured E. from N.W. corner Sec. 6
Government distance on straight line and fixed Sec. corner Jan 20-1903 & set Mount.

In Establishing the $\frac{1}{4}$ Corner on the N of Section 5 prorated E and W and
fixed $\frac{1}{4}$ corner Jan 21-1903 and set Mount.

Fixed the center of Section 5 by intersection Jan 21-1903 and set Mount.