

S. E. COR. SEC. 23, T30, R22

MONU. No. 223

Manhole at intersection. See Survey Book No. 1 for location check. Set cast irons on line to N. and W. 33 ft. out from corner. 8-25-75

Re-tied monu. 3-22-76. @ 37°

Checked short ties (>100'), O.K., 6-25-91

Checked Short Ties checked on 6/12/98 Jc D.S

RETIED WITNESS MONU'S 3-29-05

REPLACE MONUMENT FOR 223W AFTER MONUMENT WAS DESTROYED DURING A WATERMAIN BREAK, DECEMBER, 2005; RESET 20"

SI MONUMENT USING TIES OF RECORD

6-16-06

Retied monus, 223N and 223W 7-19-10

SEE BACK BOOK FOR 223-N 223(N&W) 223

