

• Irons shown in red were placed as per location as per Milner W. Carley & Assoc. survey. Their survey used a brass plug west of the granite as the section corner (See ties to monu. NO. 267). As they are placed, they do not match the legal description.

• Irons shown in green were placed as stated above but were moved west to match the iron found 43' from E as per Mr. Joe Valento had insisted. Neither as is or as Milner Carley survey, they do not match the legal description because of R.R. R/W.

